Home Inspection Report



We only overlook the lake.

Inspection Date:

Prepared For:

Prepared By:

Assurance Home inspections, LLC
Brian Nabozny
522 26th Avenue East
Ashland, WI 54806
715-292-2707
bnabozny@me.com

Report Number:

Inspector:

Brian J Nabozny

Report Overview

THE HOUSE IN PERSPECTIVE

Well Built/Maintained

CONVENTIONS USED IN THIS REPORT

SATISFACTORY - Indicates the component is functionally consistent with its original purpose but may show signs of normal wear and tear and deterioration.

MARGINAL - Indicates the component will probably require repair or replacement anytime within five years.

POOR - Indicates the component will need repair or replacement now or in the very near future.

MAJOR CONCERNS - A system or component that is considered significantly deficient or is unsafe.

SAFETY HAZARD - Denotes a condition that is unsafe and in need of prompt attention.

THE SCOPE OF THE INSPECTION

All components designated for inspection in the ASHI Standards of Practice are inspected, except as may be noted in the "Limitations of Inspection" sections within this report.

It is the goal of the inspection to put a home buyer in a better position to make a buying decision. Not all improvements will be identified during this inspection. Unexpected repairs should still be anticipated. The inspection should not be considered a guarantee or warranty of any kind.

Please refer to the pre-inspection contract for a full explanation of the scope of the inspection. Visual Inspection Only

BUILDING DATA

Approximate Age: 30 years

Style: Single Family

Main Entrance Faces: South

State of Occupancy: Occupied Fully furnished

Weather Conditions: Sunny

Recent Rain: No Ground Cover: Dry

Grounds		
Service Walks		
Material Condition Comments	None Not Visible X Concrete Flagstone Gravel Brick Other: X Satisfactory Marginal Poor Trip hazard X Typical cracks Pitched towards home Settling cracks Public sidewalk needs repair Walks on the west exterior had some settlement toward the house, repair and/or replace as needed.	
Driveway/Park	ing	
Material Condition	None ☐ Not Visible ☐ Concrete ☐ Asphalt ☐ Gravel/Dirt ☐ Brick ☐ Other: ☐ Satisfactory ☐ Marginal ☐ Poor ☐ Settling Cracks ☐ Pitched towards home ☐ Trip hazard ☐ Fill cracks and seal	
Comments	Driveway had some settlement, but is usable.	
Porch		
Condition Support Pier Floor	X None	
Stoops/Steps		
Material Condition	None X Concrete X Wood Other: □ Railing/Balusters recommended X Satisfactory □ Marginal □ Poor □ Safety Hazard □ Uneven risers □ Rotted/Damaged □ Cracked	
Comments	Settled Railroad tie on top tread of upper level deck stairs was loose presenting a possible safety hazard.	
Patio		
Material Condition	None X Concrete ☐ Flagstone ☐ Kool-Deck ☐ Brick ☐ Other: X Satisfactory ☐ Marginal ☐ Poor X Settling cracks ☐ Trip hazard ☐ Pitched towards home (see remarks) ☐ Drainage provided X Typical cracks	
Comments	Patio had some cracking and settlement, but was in usable condition.	
Deck/Balcony		
Material Condition Finish	None Not Visible Wood Metal Composite Railing/Balusters recommended Satisfactory Marginal Poor Wood in contact with soil Treated Painted/Stained Other: Safety Hazard Improper attachment to house Railing loose	
Comments	Deck appeared to be in satisfactory condition, seal as needed. Deck joists are further than 16" apart.	
Deck/Patio/Por	ch Covers X None	
Condition	☐ Satisfactory ☐ Marginal ☐ Poor ☐ Posts/Supports need Repair ☐ Earth to wood contact ☐ Moisture/Insect damage	
Recommend	Metal Straps/Bolts/Nails/Flashing Improper attachment to house	
Fence/Wall		
Type Condition Gate	Not evaluated X None Brick Block Wood Metal Chain Link Rusted Vinyl Satisfactory Marginal Poor Typical cracks Loose Blocks/Caps N/A Satisfactory Marginal Poor Planks missing/damaged Operable: Yes No	

Grounds	
Landscaping aff	fecting foundation
Negative Grade	N/A East X West X North South Satisfactory Recommend additional backfill Recommend window wells/covers X Trim back trees/shrubberies Wood in contact with/improper clearance to soil
Comments	General site drainage was properly sloping away from the house. Trees need to be trimmed away from the house.
Retaining wall	None
Material Condition	Brick X Concrete Concrete block Other: X Railroad ties Timbers Satisfactory Marginal Poor Safety Hazard Leaning/cracked/bowed Drainage holes recommended
Hose bibs	
Condition Operable	N/A X Satisfactory

\mathbf{Roof}
Roof Visibility None X All Partial Limited By:
Inspected From X Roof Ladder at eaves Ground With Binoculars
Type
Ventilation System □ Not Present Type ▼ Soffit Ridge Foof Turbine Powered Other: Comments Recommend adding a ridge vent when roof is replaced.
Material
Valleys N/A Material Not Visible Galv/Alum X Asphalt Lead Copper Other: Condition Not Visible Satisfactory X Marginal Poor Holes Rusted Recommend Sealing
Condition of Roof Coverings Roof #1
Evidence of Leakage Roof covering showed signs of curling, cracking and aging. Roof appeared to be nearing end of its useful life, budget to replace soon.
Skylights X N/A Not Visible Condition Cracked/Broken Satisfactory Marginal Poor
Plumbing Vents Not Visible Not Present Condition Satisfactory Marginal Poor

Exterior

L'AUCI IOI	
Chimney(s)	
Viewed From	None Location(s): Roof peak Roof
Gutters/Scuppe	
Condition Material Leaking	None Satisfactory Marginal Poor Rusting Downspouts needed Recommend repair/replace Needs to be cleaned Copper Vinyl/Plastic Galvanized/Aluminum Other: Corners Joints Hole in main run
Attachment	Loose Missing spikes Improperly sloped
Extension neede	ed North South East West Gutters were in overall adequate condition.
Siding	Gutters were in overall adequate condition.
Material	Stone Slate Block/Brick Fiberboard Fiber-cement Stucco EIFS* Not Inspected Asphalt X Wood Metal/Vinyl Other: X Typical cracks X Peeling paint Monitor X Wood rot Loose/Missing/Holes
Condition Comments	X Satisfactory ☐ Marginal ☐ Poor X Recommend repair/painting Siding was showing some wear, but still in functional condition. Siding was in need of normal painting / staining maintenance.
Material Condition	X Wood ☐ Fiberboard ☐ Aluminum/Steel ☐ Vinyl ☐ Stucco X Recommend repair/painting ☐ Damaged wood ☐ Other: X Satisfactory ☐ Marginal ☐ Poor
Comments	Trim was in need of normal painting maintenance.
Soffit	The state of the s
Material	None X Wood ☐ Fiberboard ☐ Aluminum/Steel ☐ Vinyl ☐ Stucco X Recommend repair/painting ☐ Damaged wood ☐ Other:
Condition	X Satisfactory Marginal Poor
Fascia	□ None
Material	X Wood Fiberboard Aluminum/Steel Vinyl Stucco X Recommend repair/painting
Condition	□ Damaged wood □ Other: X Satisfactory □ Marginal □ Poor
Flashing	
Material	X None Wood ☐ Fiberboard ☐ Aluminum/Steel ☐ Vinyl ☐ Stucco ☐ Recommend repair/painting Damaged wood ☐ Other:
Condition	Satisfactory Marginal Poor

Exterior	
nal Poor ndows/doors/masonry ledges/corners/utility penetrations, recommend removing and replacing.	
mend repair/replace damaged screens Failed/fogged insulated glass Marginal Recommend repair/painting Failed/fogged insulated glass Marginal Aluminum/Vinyl clad installed	
Condition: Condition: Recommend repair/painting Wood/Metal comb. Metal N/A	
Poured concrete Post-Tensioned concrete Not Visible Other: nal Monitor Have Evaluated Not Evaluated Satisfactory Marginal Monitor Have Evaluated	
head	
Masonry Other:	
X Satisfactory Marginal Poor Missing Replace	

Page	q
rage	フ

Exterior
Unit #1
Unit #2

	Fage 1
-	Garage/Carport
Туре	None X Attached Detached X 1-Car 2-Car 3-Car 4-Car
Automatic Ope	X Yes No X Operable Inoperable
Safety Reverse	X Operable Not Operable Need(s) adjusting Safety hazard Photo eyes and pressure reverse tested
Roofing Material Comments	X Same as house Type: Asphalt Approx. age 30 years Approx. layers 1 Roof appeared to be nearing end of its useful life, budget to replace soon.
Gutters/Eavest Condition	X Satisfactory Marginal Poor X Same as house
Siding	
Material Condition Comments Trim	N/A X Same as house X Wood
Material Condition	N/A X Same as house X Wood Aluminum Vinyl X Satisfactory Marginal Poor Recommend repair/replace X Recommend painting
Floor Material Condition Burners less th	X Concrete Gravel Asphalt Dirt Other: X Satisfactory X Typical cracks Large settling cracks Recommend evaluation/repair Safety hazard an 18" above floor X N/A Yes No
Sill Plates	Not Visible ☐ Floor level ☒ Elevated ☐ Rotted/Damaged ☐ Recommend repair
Overhead Door	$\mathbf{r}(\mathbf{s})$
Material Condition	N/A Wood Fiberglass Masonite X Metal Recommend repair X Satisfactory Marginal Poor Hardware loose Safety Cable Recommended Weatherstripping missing/damaged Loose/missing
Recommend Pr Comments	riming/Painting Inside & Edges Yes X No Garage door and opener was in normal working order.
Exterior Service Condition	© Door
1	

Garage/Carport
Electrical Receptacles N/A Not Visible Reverse polarity Yes X No Open ground Yes X No Safety Hazard GFCI Present Yes X No Operable: Yes No Handyman/extension cord wiring
Comments Recommend GFCI Receptacles Outlets were randomly tested and had correct polarity, except as noted.
Fire Separation Walls & Ceiling N/A Present Missing Condition Satsifactory Recommend repair Holes walls/ceiling Safety hazard(s) Moisture Stains Present Yes No Typical Cracks Yes No Fire door Not verifiable Not a fire door Needs repair Satisfactory Auto closure N/A Satisfactory Inoperative Missing Comments Firewall between garage and living area not present - Potential Safety Hazard

Kitchen	
Comments	X Satisfactory ☐ Marginal ☐ Recommend repair/caulking Counter top has normal wear.
Cabinets Comments	X Satisfactory Marginal Recommend repair/adjustment Cabinets have normal wear.
Functional flow Comments	X Satisfactory ☐ Corroded ☐ Chipped ☐ Cracked ☐ Recommend repair inage X Satisfactory ☐ Marginal ☐ Poor ☐ X Satisfactory ☐ Marginal ☐ Poor ☐ Water flow was normal with several fixtures operated at the same time.
Walls & Ceiling Condition	X Satisfactory ☐ Marginal ☐ Poor ☐ Typical cracks ☐ Moisture stains
Heating/Coolin	g Source X Yes No
Floor Condition	X Satisfactory ☐ Marginal ☐ Poor ☐ Sloping X Squeaks
Receptacles pro GFCI	X N/A

		Page 1
	Kitchen(1)	
Countertops Comments Cabinets	X Satisfactory ☐ Marginal ☐ Recommend repair/caulking Counter top has normal wear.	
Comments Plumbing Faucet Leaks	X Satisfactory Marginal Recommend repair/adjustment Cabinets have normal wear. Yes X No	-
Functional flow Comments	X Satisfactory ☐ Corroded ☐ Chipped ☐ Cracked ☐ Recommend repair inage X Satisfactory ☐ Marginal ☐ Poor ▼ X Satisfactory ☐ Marginal ☐ Poor Water flow was normal with several fixtures operated at the same time.	
Walls & Ceiling Condition Comments	X Satisfactory Marginal Poor Typical cracks X Moisture stains Old moisture stains visible on ceiling above range. Drywall was not holding excessive moisture at the time of inspection. Recommend painting and monitoring this area for future leaks.	
Heating/Coolin	g Source X Yes No	
Floor Condition	X Satisfactory Marginal Poor Sloping Squeaks	
Dishwasher dra Receptacles pro GFCI	X N/A	

Laundry Room

Laundry	
Laundry sink	□ N/A
Faucet leaks	Yes X No
Pipes leak	Yes X No Not Visible Ons Yes X No Potential Safety Hazard
Heat source pro	esent X Yes No
Room vented	X Yes No
Dryer vented	N/A Wall Ceiling X Floor Not vented X Plastic dryer vent not recommended Not vented X Plastic dryer vent not recommended
	Not vented to exterior Recommend repair Safety hazard
Electrical GFCI present	Open ground/reverse polarity: Yes X No Safety hazard
Appliances	Yes X No Operable: Yes No X Recommend GFCI Receptacles X Washer X Dryer Water heater Furnace/Boiler
Washer hook-u	p lines/valves X Satisfactory Leaking Corroded Not Visible
Gas shut-off va	Ive N/A X Yes No Cap Needed Safety hazard Not Visible
Comments	Washer/dryer not evaluated.

Rathroom

Datili vvili
Bath
Location First floor bath Sinks Faucet leaks: ☐ Yes ☐ No ☐ N/A Faucet leaks: ☐ Yes ☐ No ☐ N/A Faucet leaks: ☐ Yes ☐ No ☐ N/A Faucet leaks: ☐ Yes ☐ No ☐ No ☐ No ☐ N/A Faucet leaks: ☐ Yes ☐ No ☐ N
Tubs
Whirlpool Yes X No Operable: Yes No Not tested No access door Shower/Tub area Ceramic/Plastic X Fiberglass Masonite Other:
Condition: X Satisfactory Marginal Poor Rooted floors Caulk/Grouting needed: Yes X No Where:
Drainage X Satisfactory Marginal Poor Water flow X Satisfactory Marginal Poor
Moisture stains present Yes Walls Ceilings Cabinetry Doors Satisfactory Marginal Poor Window None Satisfactory Marginal Poor
Receptacles present X Yes No Operable: X Yes No
Open ground/Reverse polarity Yes No Potential Safety Hazard Recommend GFCI Receptacles Heat source present Yes No
Exhaust fan X Yes No Operable: X Yes No Noisy

Bathroom

Dathroom
Bath
Location Master bath
Sinks Faucet leaks: Yes X No Pipes leak: Yes X No
Tubs
Showers N/A Faucet leaks: Yes X No Pipes leak: Yes No X Not Visible
Toilet Bowl loose: Yes X No Operable: X Yes No Cracked bowl Toilet leaks
Whirlpool Yes X No Operable: Yes No Not tested No access door Shower/Tub area Ceramic/Plastic X Fiberglass Masonite Other:
Condition: X Satisfactory Marginal Poor Rooted floors Caulk/Grouting needed: Yes X No
Where:
Drainage X Satisfactory Marginal Poor
Water flow X Satisfactory Marginal Poor
Moisture stains present Yes X No Walls Ceilings Cabinetry
Doors X Satisfactory Marginal Poor
Window None X Satisfactory Marginal Poor Receptacles present X Yes No Operable: X Yes No
GFCI X Yes No Recommend GFCI Operable: Yes No
Open ground/Reverse polarity Yes No X Potential Safety Hazard Recommend GFCI Receptacles
Heat source present X Yes No
Exhaust fan X Yes No Operable: X Yes No Noisy
Comments Recommend cleaning/tightening north vanity faucet aerator.

Rathroom

	Datin voin
Bath	
Location	Basement bath
Sinks	Faucet leaks: Yes X No Pipes leak: Yes X No
Tubs	N/A Faucet leaks: Yes X No Pipes leak: Yes No X Not Visible
Showers	N/A Faucet leaks: Yes X No Pipes leak: Yes No X Not Visible
Toilet	Bowl loose: Yes X No Operable: X Yes No Cracked bowl Toilet leaks
Whirlpool	Yes No Operable: Yes No Dot tested No access door
Shower/Tub ar	
	Condition: \overline{X} Satisfactory \overline{X} Marginal \overline{X} Poor \overline{X} Rooted floors Caulk/Grouting needed: \overline{X} No
	Where:
Drainage	X Satisfactory Marginal Poor
Water flow	X Satisfactory Marginal Poor
Doors	spresent Yes X No Walls Ceilings Cabinetry X Satisfactory Marginal Poor
Window	X None Satisfactory Marginal Poor
	esent X Yes No Operable: X Yes No
GFCI	X Yes No Recommend GFCI Operable: Yes No
	Reverse polarity Yes X No Potential Safety Hazard Recommend GFCI Receptacles
Heat source pro	esent Yes X No
Exhaust fan	X Yes No Operable: X Yes No X Noisy

Room
Room
Location: First floor SE Type: LIVING ROOM Unit #: Walls & Ceiling Satisfactory Marginal Poor Typical cracks Damage Moisture stains Yes No Where: Floor Satisfactory Marginal Poor Squeaks Slopes Tripping hazard Ceiling fan None Satisfactory Marginal Poor Recommend repair/replace Electrical Operable: Yes No Switches: Yes No Soperable Receptacles: Yes No Operable Open ground/Reverse polarity: Yes No Safety hazard Cover plates missing
Heating source present X Yes No Holes: Doors Walls Ceilings Bedroom Egress restricted X N/A Yes No Doors Satisfactory Marginal Poor Cracked glass Evidence of leaking insulated glass Broken/Missing hardware
Windows X Satisfactory Marginal Poor Cracked glass Evidence of leaking insulated glass Broken/Missing hardware

	Room
Room	
	Location: First floor South center Type: DINING ROOM Unit #: Satisfactory Marginal Poor Typical cracks Damage Yes X No Where: Satisfactory Marginal Poor Squeaks Slopes Tripping hazard None Satisfactory Marginal Poor Recommend repair/replace
Electrical	Operable: X Yes No Switches: X Yes No X Operable Receptacles: X Yes No X Operable Open ground/Reverse polarity: Yes X No Safety hazard Cover plates missing
Heating source Bedroom Egres Doors	present
Windows	☐ Broken/Missing hardware X Satisfactory ☐ Marginal ☐ Poor ☐ Cracked glass ☐ Evidence of leaking insulated glass
	☐ Broken/Missing hardware

Room
Room
Location: First floor NE Type: BEDROOM Unit #: Walls & Ceiling \[\text{Satisfactory} \] Marginal \[\text{Poor} \] Poor \[\text{Typical cracks} \] Damage Moisture stains \[\text{Yes} \[\text{No} \] Where: Floor \[\text{Satisfactory} \] Marginal \[\text{Poor} \] Squeaks \[\text{Slopes} \] Tripping hazard Ceiling fan \[\text{X None} \] Satisfactory \[\text{Marginal} \] Marginal \[\text{Poor} \] Recommend repair/replace Electrical \[\text{Operable:} \[\text{X Yes} \] No \[\text{No perable} \] Receptacles: \[\text{X Yes} \] No \[\text{X Operable} \] Open ground/Reverse polarity: \[\text{Yes} \] No \[\text{Safety hazard} \] Cover plates missing
Heating source present X Yes No Holes: Doors Walls Ceilings Bedroom Egress restricted N/A Yes X No Doors X Satisfactory Marginal Poor Cracked glass Evidence of leaking insulated glass Broken/Missing hardware Windows X Satisfactory Marginal Poor Cracked glass Evidence of leaking insulated glass
Broken/Missing hardware

Room
Room
Location: First floor NW Type: BEDROOM Unit #: Walls & Ceiling \overline{X} Satisfactory Marginal Poor Typical cracks Damage Moisture stains Yes \qvac X No Where: Floor X Satisfactory Marginal Poor Squeaks Slopes Tripping hazard Ceiling fan X None Satisfactory Marginal Poor Recommend repair/replace Electrical Operable: X yes No Switches: X yes No X Operable Receptacles: X yes No X Operable Operable Poor Safety hazard Cover plates missing Heating source present X yes No Holes: Doors Walls Ceilings
Bedroom Egress restricted N/A Yes No Doors Satisfactory Marginal Poor Cracked glass Evidence of leaking insulated glass Broken/Missing hardware
Windows X Satisfactory Marginal Poor Cracked glass Evidence of leaking insulated glass Broken/Missing hardware

Room
Room
Location: First floor SW Type: MASTER BEDROOM Unit #: Walls & Ceiling \[\text{Satisfactory} \] Marginal \[\text{Poor} \] Poor \[\text{Typical cracks} \] Damage Moisture stains \[\text{Yes} \] No \[\text{Where:} \] Floor \[\text{X} \text{Satisfactory} \] Marginal \[\text{Poor} \] Squeaks \[\text{Slopes} \] Tripping hazard Ceiling fan \[\text{None} \] None \[\text{X} \text{Satisfactory} \] Marginal \[\text{Poor} \] Poor \[\text{Recommend repair/replace} \] Electrical \[\text{Operable:} \[\text{X} \text{Yes} \] No \[\text{No Switches:} \[\text{X} \text{Yes} \] No \[\text{No perable} \]
Open ground/Reverse polarity:
Windows Satisfactory Marginal Poor Cracked glass Evidence of leaking insulated glass Broken/Missing hardware

Room
Room
Location: Basement Type: FAMILY ROOM Unit #: Walls & Ceiling \(\) Satisfactory \(\) Marginal \(\) Poor \(\) Typical cracks \(\) Damage Moisture stains \(\) Yes \(\) No Where: Floor \(\) Satisfactory \(\) Marginal \(\) Poor \(\) Squeaks \(\) Slopes \(\) Tripping hazard Ceiling fan \(\) None \(\) Satisfactory \(\) Marginal \(\) Poor \(\) Recommend repair/replace Ceiling fan \(\) None \(\) Satisfactory \(\) No Switches: \(\) Yes \(\) No \(\) Operable Receptacles: \(\) Yes \(\) No \(\) Operable Open ground/Reverse polarity: \(\) Yes \(\) No \(\) Safety hazard \(\) Ceilings Heating source present \(\) Yes \(\) No Holes: \(\) Doors \(\) Walls \(\) Ceilings
Bedroom Egress restricted X N/A Yes No Doors X Satisfactory Marginal Poor Cracked glass Evidence of leaking insulated glass
Broken/Missing hardware Windows X Satisfactory Marginal Poor Cracked glass Evidence of leaking insulated glass Broken/Missing hardware

	Room
Room	
Walls & Ceiling Moisture stains Floor Ceiling fan Electrical	Location: Basement NW Type: BEDROOM Unit #: X Satisfactory Marginal Poor Typical cracks Damage Yes X No Where: X Satisfactory Marginal Poor Squeaks Slopes Tripping hazard X None Satisfactory Marginal Poor Recommend repair/replace Operable: Yes No Switches: Yes No X Operable Receptacles: Yes No X Operable Open ground/Reverse polarity: Yes X No Safety hazard Cover plates missing Operable Yes X No Holes: Doors Walls Ceilings
Bedroom Egress Doors	S restricted N/A X Yes No No Satisfactory Marginal Poor Cracked glass Evidence of leaking insulated glass Broken/Missing hardware Statement Poor Cracked glass Evidence of leaking insulated glass Statement Poor Cracked glass Evidence of leaking insulated glass Statement Poor Cracked glass Evidence of leaking insulated glass Statement Poor Cracked glass Evidence of leaking insulated glass Statement Poor Cracked glass Evidence of leaking insulated glass Statement Poor Cracked glass Cracked glass Poor Poor Cracked glass Poor Cracked gl
Windows	Satisfactory Marginal Poor Cracked glass Evidence of leaking insulated glass Broken/Missing hardware
Comments	Bedroom is missing an egress window.

Room
Room
Location: Basement SW Type: BEDROOM Unit #: Walls & Ceiling X Satisfactory
Open ground/Reverse polarity:
Broken/Missing hardware
☐ Broken/Missing hardware

Room
Room
Location: Basement North center Type: office/sitting room Unit #: Walls & Ceiling \overline{X} Satisfactory Marginal Poor Typical cracks Damage Moisture stains Yes \overline{X} No Where: Floor Satisfactory Marginal Poor Squeaks Slopes Tripping hazard Ceiling fan None Satisfactory Marginal Poor Recommend repair/replace Electrical Operable: Yes No Switches: Yes No Operable Receptacles: Yes No Operable
Open ground/Reverse polarity:

Interior

Fireplace	
Type Material Miscellaneous Damper modifi Hearth extension Mantel Physical conditi Comments	None Location(s): Living room/Family room Gas X Wood Solid fuel burning stove Electric Ventless Masonry Metal (pre-fabricated) Metal insert X Cast Iron Blower built-in Operable: Yes X No Damper operable: Yes No Open joints or cracks in firebrick/panels should be sealed Fireplace doors need repair ed for gas operation N/A Yes X No Damper missing on adequate X Yes No N/A X Secure Loose Recommend repair/replace ion X Satisfactory Marginal Poor X Recommend having flue cleaned and re-examined Not evaluated Recommend having flue cleaned and reexamined.
Stairs/Steps/Ba	lconies
Handrail Risers/Treads	None X Satisfactory Marginal Poor Loose/Missing X Satisfactory Marginal Poor Safety hazard Hand Rail/Railing/Balusters recommended X Satisfactory Marginal Poor Risers/Treads uneven Trip hazard
	Monoxide detectors
Present Comments	X Smoke detector: Operable: X Yes No Not tested Recommend additional X CO detector: Operable: Yes X No Not tested Recommend additional Smoke detectors were missing batteries at time of inspection.
Attic/Structure	/Framing/Insulation
Location	N/A Stairs Pulldown X Scuttlehole/Hatch No Access Other: X Access panel In the attic Other Hallway X Bedroom Closet Garage Other
Access limited l	·
Flooring Insulation	Complete Partial X None Fiberglass Batts X Loose Cellulose Foam Other Vermiculite Rock wool
Installed in	Depth 10-12" Recommend baffles at eaves Damaged Displaced Missing Compressed Rafters/Trusses Walls X Between ceiling joists Underside of roof deck Not Visible
Von en hourious	Recommend additional insulation
Vapor barriers Ventilation	Kraft/foil faced Plastic sheeting X Not Visible Improperly installed
	X Ventilation appears adequate ☐ Recommend additional ventilation to Attic: X Yes ☐ No X Recommend repair Outside: ☐ Yes ☐ No ☐ Not Visible
HVAC Duct	Attic: Tes No Recommend repair Outside: Tes No Not Visible No No Not Visible No No No No No No No
	Recommend Insulation
	□ N/A X Satisfactory □ Needs repair □ Not Visible □
	Dlems observed ☐ Yes X No ☐ Recommend repair ☐ Recommend structural engineer
Roof structure	Rafters X Trusses Wood Metal Collar ties Purlins Knee wall Not Visible Other:
Ceiling joists	X Wood Metal Not Visible
Sheathing	X Plywood OSB Planking Rotted Stained Delaminated
Evidence of con	
Evidence of mo	isture Yes X No
Evidence of lead	
Firewall between	en units X N/A Yes No Needs repair/sealing
Electrical	▼ Open junction box(es) ☐ Handyman wiring ☐ Visible knob-and-tube
Comments	Recommend venting bathroom exhaust fan to exterior with a properly insulated flexible duct line. Fan currently vents
	directly into the attic. There are also junction boxes for attic lights that are not covered properly. The drywall access panel cover panel should be insulated with rigid foam to minimize heat loss into the attic in this area as well.

	Basement
Handrail	X Satisfactory
Condition Material Horizontal crack Step cracks Vertical cracks Covered walls Movement appa Indication of mo	X North South East West North South East West North South East West
Walls Comments	Typical cracks.
Floor Material Condition Comments Seismic bolts	X Concrete
Drainage Sump pump Floor drains	Yes X No Working Not working Needs cleaning Pump not tested X Yes Not Visible X Drains not tested
Condition Material Comments Columns	Not Visible Satisfactory Marginal Poor Stained/Rusted Steel ∑Wood Concrete LVL Not Visible Recommend a bearing point of 3" to support beam in utility room. See photo. Not Visible
Condition Material	
Joists Condition Material	Not Visible X Satisfactory
Subfloor Comments	Not Visible ☐ Indication of moisture stains/rotting Visible portions were in satisfactory condition at time of inspection.

Plumbing

Water service
Main shut-off location: Basement utility room Water entry piping Not Visible X Copper/Galv. PVC Plastic CPVC Plastic Polybutylene Plastic PEX Plastic Lead Lead other than solder joints Yes No X Unknown Service entry
Visible water distribution piping X Copper Galvanized PVC Plastic CPVC Plastic Polybutylene Plastic X PEX Plastic Other:
Condition
Pipes Supply/Drain
Condition X Satisfactory Marginal Poor Support/Insulation X N/A Type:
Traps proper P-Type X Yes No P-traps recommended Drainage X Satisfactory Marginal Poor Interior fuel storage system X N/A Yes No Leaking: Yes No
Fuel line N/A Copper Brass X Black iron Stainless steel X CSST Not Visible Condition X Satisfactory Marginal Poor Recommend plumber evaluate
Main fuel shut-off location N/A exterior at gas meter
Well pump N/A Submersible X In basement Well house Well pit Shared well Pressure gauge operable X Yes No Well pressure 48 psi Not Visible
Sanitary/Grinder pump X N/A Sealed crock: Yes No Check valve: Yes No Shut-off valve: Yes No Vented Yes No Operable: Yes No
Water heater #1 N/A Brand Name: State Serial # G83406899 Capacity: 50 gallon Approx. age: 30 years Type
Water heater #2

Plumbing			
Vater softener			
N/A X Present Loop installed X Yes No Clumbing hooked up X Yes No Clumbing leaking Yes X No			

Heating System

	meaning System
Heating system	
Unit #1	Brand name: N/A Approx. age: Unknown Model #: Serial #
Unit #2	Brand name: N/A Approx. age: Unknown Model #: Serial #
Energy source	Gas LP Oil Electric Solid fuel
Warm air syste	
Heat exchanger	N/A Sealed Not Visible Visual w/mirror Flame distortion Rusted
C	Carbon/soot buildup
Carbon monox CO test	
	Tester: venting present N/A Yes No
Controls	Disconnect: Yes No Normal operating and safety controls observed
Distribution	Metal duct Insulated flex duct Cold air returns Duct board Asbestos-like wrap
2 1501 15 (1010)	Safety Hazard
Flue piping	□ N/A □ Satisfactory □ Rusted □ Improper slope □ Safety hazard □ Recommend repair/replace
Filter	Standard Electrostatic Satisfactory Needs cleaning/replacement Missing
	Electronic (not tested)
	n by thermostat ☐ Fired ☐ Did not fire Proper operation: ☐ Yes ☐ No ☐ Not tested
Heat pump	N/A Supplemental electric Supplemental gas
	N/A Satisfactory Marginal Poor Water/Sand Observed: Yes No
	dition Satisfactory Marginal Poor Recommended HVAC technician examine
	dition ☐ Satisfactory ☐ Marginal ☐ Poor ☐ Recommended HVAC technician examine rated due to ☐ Exterior temperature ☐ Other:
System not ope	Tated due to Exterior temperature Other.
D •1	
Boiler system	N/A Drand name: Wail Mal sin Approx aga: 20 years Madal # CCM 6 Sarial # unknown
Energy source	N/A Brand name: Weil-McLain Approx. age: 30 years Model #: CGM-6 Serial # unknown X Gas □ LP □ Oil □ Electric □ Solid fuel
Distribution	Hot water X Baseboard Steam Radiator Radiant floor
Circulator	X Pump Gravity X Multiple zones
Controls	Temp/pressure gauge exist: X Yes No Operable: X Yes No
Oil fired units	Disconnect: Yes No
Combustion air	venting present Yes X No N/A
Relief valve	Yes X No Missing Extension proper: Yes X No X Recommend repair/replace
Operated	When turned on by thermostat: X Fired Did not fire
Operation	Satisfactory: X Yes No Recommend HVAC technician examine before closing
Comments	Boiler was in normal working order at the time of the inspection.
Other systems	
Proper operation	N/A X Electric baseboard ☐ Radiant ceiling cable ☐ Gas space heater ☐ Solid fuel burning stove
System condition	
System condition	M M Satisfactory Marginar 1 oof Recommend II vac recinician Examine

Electric/Cooling System

Main panel	
Adequate Clearance to Amperage/Voltage Breakers/Fuses X Breakers grounded SefCI breaker Yes Main wire Condition	Yes No Not Visible S X No Operable: Yes No S X No Operable: Yes No Not Tested S X Aluminum Not Visible Double tapping of the main wire S Satisfactory Marginal Poor S Aluminum Solid Branch Aluminum Not Visible Safety Hazard
Sub panel(s) No Reason	ne apparent Location 1: Garage Location 2: Location 3: Panel not accessible Not evaluated
Branch wire X Co	pper Aluminum Safety hazard Neutral/ground separated: X Yes No
Condition X Sat	l isolated: XYes No isfactory Marginal Poor Recommend separating/isolating neutrals commend electrician repair/evaluate box
	g in sub-panel was not complete at time of inspection.
Heat Pump - A/C Unit	_
Evaporator coil Sat Refrigerant lines Condensate line/drain Secondary condensate Operation Differe Condition Sat	ntral system
Evaporator coil Sat Refrigerant lines Condensate line/drain Secondary condensate Operation Differe Condition Sat	Central system

Report Summary

Items Not Operating

Major Concerns

Item(s) that have failed or have potential of failing soon.

Potential Safety Hazards

- *Missing GFCI protection to exterior outlet above upper deck on south wall.
- *Loose railroad tie on top tread of deck stairs.
- *Missing switch/junction box coverplates in garage.
- *Missing fire separation wall between garage and living area.
- *Missing batteries in smoke detectors.
- *Open light junction boxes in attic.
- *Missing switch/outlet coverplates in basement utility room.
- *Boiler relief valve is missing proper copper extension to the floor.


Deferred Cost Items

Items that have reached or are reaching their normal life expectancy or show indications that they may require repair or replacement anytime during the next five (5) years.

- *Asphalt shingle roof is in marginal condition.
- *Dishwasher leaks onto floor after use. Recommend repair/replacement.
- *Weil-McLain boiler due to its age.
- *Water heaters more than 5+ years old.

Improvement Items


Items To Monitor



Recommend trimming back tree limbs from exterior to prevent excessive wear.




Asphalt architectural roof is showing normal signs of wear due to its age and is in marginal condition.





Metal roof over north garage addition was in satisfactory condition at the time of inspection.

Ridge cap shingles are cracked.







West garage exterior.



200 amp main electrical panel in basement utility room.



Sub-panel in garage. Wiring is not complete in this panel.



Weil-McLain boiler was in proper working order at time of inspection.



State 50 gallon water.



Well pressure tank, pump, and water softener system.



Recommend a bearing point of 3" on both sides of header beam in basement utility room.

Photos



Missing coverplates present a safety hazard.



Missing electrical coverplates in garage present a safety hazard.



Electrical safety hazard.



Recommend painting siding to extend useable life.

Photos





Visible wood decay along bottom coarses if siding.

Loose railroad tie on top tread presents a safety hazard.



Exterior outlet is missing GFCI protection.

Grounds Remarks

SERVICE WALKS/DRIVEWAYS

Spalling concrete cannot be patched with concrete because the new will not bond with the old. Water will freeze between the two layers, or the concrete will break up from movement or wear. Replacement of the damaged section is recommended. Walks or driveways that are close to the property should be properly pitched away to direct water away from the foundation. Asphalt driveways should be kept sealed and larger cracks filled so as to prevent damage from frost.

PATIOS

Patios that have settled towards the structure should be mudjacked or replaced to assure proper pitch. Improperly pitched patios are one source of wet basements/crawlspaces.

EXTERIOR WOOD SURFACES

All surfaces of untreated wood need regular applications of paint or special chemicals to resist damage. Porch or deck columns and fence posts which are buried in the ground and made of untreated wood will become damaged within a year or two.

Decks should always be nailed with galvanized, stainless steel or aluminum nails. Decks that are not painted or stained should be treated with a water sealer.

GRADING AND DRAINAGE

Any system of grading or landscaping that creates positive drainage (moving water away from the foundation walls) will help to keep a basement and crawlspace dry. Where negative grade exists and additional backfill is suggested, it may require digging out around the property to get a proper pitch. Dirt shall be approximately 6" below the bottom sill and should not touch wood surfaces.

Flower beds, loose mulched areas, railroad ties and other such landscaping items close to the foundation trap moisture and contribute to wet basements. To establish a positive grade, a proper slope away from the house is 1" per foot for approximately 5-6 feet. Recommend ground cover planting or grass up to foundation.

ROOF AND SURFACE WATER CONTROL

Roof and surface water must be controlled to maintain a dry basement and crawlspace. This means keeping gutters cleaned out and aligned, extending downspouts, installing splashblocks, and building up the grade so that roof and surface water is diverted away from the building

WINDOW WELLS

The amount of water which enters a window well from falling rain is generally slight, but water will accumulate in window wells if the yard is improperly graded. Plastic window well covers are useful in keeping out leaves and debris.

RETAINING WALLS

Retaining walls deteriorate because of excessive pressure buildup behind them, generally due to water accumulation. Conditions can often be improved by excavating a trench behind the retaining wall and filling it with coarse gravel. Drain holes through the wall will then be able to relieve the water pressure.

Retaining walls sometime suffer from tree root pressure or from general movement of topsoil down the slope. Normally, these conditions require rebuilding the retaining wall.

RAILINGS

It is recommended that railings be installed for any stairway over 3 steps and porches over 30" for safety reasons. Balusters for porches, balconies, and stairs should be close enough to assure children cannot squeeze through.

DEFINITIONS

SATISFACTORY (Sat.) - Indicates the component is functionally consistent with its original purpose but may show signs of normal wear and tear and deterioration.

MARGINAL (Marg.) - Indicates the component will probably require repair or replacement anytime within five years.

POOR - Indicates the component will need repair or replacement now or in the very near future.

Roof Remarks

Valleys and Flashings that are covered with shingles and/or tar or any other material are considered not visible and are not part of the inspection.

Tar and Gravel Roofs - This type of covering on a pitched roof requires ongoing annual maintenance. We recommend that a roofing contractor evaluate this type of roof. Infra-red photography is best used to determine areas of potential leaks.

Flat roofs are very vulnerable to leaking. It is very important to maintain proper drainage to prevent the ponding of water. We recommend that a roofing contractor evaluate this type of roof.

ROOF TYPE	LIFE EXPECTANCY	SPECIAL REMARKS
Asphalt Shingles	15-20 years	Used on nearly 80% of all residential roofs requires little maintenance.
Asphalt Multi-Thickness	20-30 years	Heavier and more durable than regular asphalt shingles.
Shingles*		
Asphalt Interlocking.	15-25 years	Especially good in high-wind areas.
Shingles*		
Asphalt Rolls	10 years	Used on low slope roofs.
Built-up Roofing	10-20 years	Used on low slope roofs, 2 to 3 times as costly as asphalt shingles.
Wood Shingles*	10-40 years**	Treat with preservative every 5 years to prevent decay.
Clay Tiles*	20 + years	Durable, fireproof, but not watertight, requiring a good subsurface base.
Cement Tiles*	20 + years	Durable, fireproof, but not watertight, requiring a good subsurface base.
Slate Shingles*	30-100 years ***	Extremely durable, but brittle and expensive.
Asbestos Cement	30-75 years	Durable, but brittle and difficult to repair.
Shingles*		
Metal Roofing	15-40 + years	Comes in sheets & shingles; should be well grounded for protection from lightning
		certain metals must be painted.
Single Ply	15-25 years	New material; not yet passed test of time.
Membrane (mfgr's	5-10 years**	Used on low slope roofs.
claim) Polyurethane		
with Elastomenic		
Coating		

^{*} Not recommended for use on low slope roof

Roof coverings should be visually checked in the spring and fall for any visible missing shingles, damaged coverings or other defects. Before re-roofing, the underside of the roof structure and roof sheathing should be inspected to determine that the roof structure can support the additional weight of the shingles.

Wood shakes and shingles will vary in aging, due to the quality of the material, installation, maintenance, and surrounding shade trees. Ventilation and drying of the wood material is critical in extending the life expectancy of the wood. Commercial preservatives are available on the market, which could be applied to wood to impede deterioration.


^{**} Depending on local conditions and proper installation

^{***} Depending on quality of slate

Exterior Remarks

Every effort has been made to evaluate the size of the service. Three wires going into the home indicate 240 volts. The total amperage can be difficult to determine. We highly recommend that ground fault circuit interrupters (G.F.C.I.) be connected to all outlets around water. This device automatically shuts the circuit off when it senses a current leak to ground. This device can be purchased in most hardware stores. G.F.C.I.'s are recommended by all outlets located near water, outside outlets, or garage outlets. Pool outlets should also be protected with a G.F.C.I.

See diagram below:



If you do have G.F.C.I.'s, it is recommended that you test (and reset) them monthly. When you push the test button, the reset button should pop out, shutting off the circuit. If it doesn't, the breaker is not working properly. If you don't test them once a month, the breakers have a tendency to stick and may not protect you when needed.

Knob and tube wiring found in older homes should be checked by an electrician to insure that the wire cover is in good condition. Under no circumstances should this wire be covered with insulation. Recess light fixtures should have a baffle around them so that they are not covered with insulation. The newer recessed fixtures will shut off if they overheat. (no representation is made as to proper recess lighting fixtures).

Federal Pacific Stab-Lok Electrical® panels may be unsafe. See www.google.com (Federal Pacific)
Aluminum wiring in general lighting circuits has a history of overheating, with the potential of a fire. If this type of wiring exists, a licensed electrical contractor should examine the whole system.

ARC FAULTS

In some areas arc faults are required for bedrooms in new homes starting in 2002. In some areas arc Faults are required for all 120 Volt circuits that are not GFCI protected in new homes starting in 2009. Upgrade as desired for enhanced safely.

REVERSE POLARITY

A common problem that surfaces in many homes is reverse polarity. This is a potentially hazardous situation in which the hot and neutral wires of a circuit are reversed at the outlet, thereby allowing the appliance to incorrectly be connected. This is an inexpensive item to correct.

Each receptacle has a brass and silver screw. The black wire should be wired to the brass screw and the white wire should go to the silver screw. When these wires are switched, this is called "Reverse polarity". Turning off the power and switching these wires will correct the problem.

Main service wiring for housing is typically 240 volts. The minimum capacity for newer homes is 100 amps though many older homes still have 60 amp service. Larger homes or all electric homes will likely have a 200 amp service.

Main service wiring may be protected by one or more circuit breakers or fuses. While most areas allow up to six main turnoffs, expanding from these panels is generally not allowed.

COOLING

Testing A/C System and Heat Pump- The circuit breakers to A/C should be on for a minimum of 24 hours and the outside temperature at least 60 degrees for the past 24 hours or an A/C system cannot be operated without possible damage to the compressor. Check the instructions in your A/C manual or on the outside compressor before starting up in the summer. Heat pump can only be tested in the mode it's running in. Outside temperature should be at least 65 for the past 24 hours to run in cooling mode.

Temperature differential, between 14-22, is usually acceptable. If out of this range, have an HVAC contractor examine it. It is not always feasible to do a differential test due to high humidity, low outside temperature, etc.

A/C CONDENSER COIL They should not become overgrown with foliage. Clearance requirements vary, but 2 feet on all sides should be considered minimal with up to 6 feet of air discharge desirable. If a clothes dryer vent is within five to ten feet, either relocate the vent or do not run when the A/C is running. The lint will quickly reduce the efficiency of the A/C unit.

Exterior Remarks

CHIMNEYS

Chimneys built of masonry will eventually need tuckpointing. A cracked chimney top that allows water and carbonic acid to get behind the surface brick/stone will accelerate the deterioration. Moisture will also deteriorate the clay flue liner. Periodic chimney cleaning will keep you apprised of the chimneys condition. The flashing around the chimney may need resealing and should be inspected every year or two. Fireplace chimneys should be inspected and evaluated by a chimney professional before using. Chimneys must be adequate height for proper drafting. Spark arrestors are recommended for a wood burning chimney, and chimney caps for fossil fuels. Unlined Chimney should be re-evaluated by a chimney technician. Have flue cleaned and re-evaluated. The flue lining is covered with soot or creosote and no representation can be made as to the condition.

NOT EVALUATED

The flue was not evaluated due to inaccessibility such as roof pitch, cap, cleanout not accessible, etc.

CRICKET FLASHING

Small, sloped structure made of metal and designed to drain moisture away from a chimney. Usually placed at the back of a chimney.

GUTTERS AND DOWNSPOUTS

This is an extremely important element in basement/crawlspace dampness control. Keep gutters clean and downspout extensions in place (4 or more). Paint the inside of galvanized gutters, which will extend the life. Shortly after a rain or thaw in winter, look for leaks at seams in the gutters. These can be recaulked before they cause damage to fascia or soffit boards. If no gutters exist, it is recommended that they be added.

SIDING

Wood siding should not come in contact with the ground. The moisture will cause rotting to take place and can attract carpenter ants. See page 34 for siding that have known problems, but are not always recognizable. Brick and stone veneer must be monitored for loose or missing mortar. Some brick and stone are susceptible to spalling. This can be caused when moisture is trapped and a freeze/thaw situation occurs. There are products on the market that can be used to seal out the moisture. This holds true for brick and stone chimneys also. Metal siding will dent and scratch. Oxidation is a normal reaction in aluminum. There are good cleaners on the market and it is recommended that they be used occasionally. Metal siding can be painted.

EIFS

This type of siding is a synthetic stucco and has experienced serious problems. It requires a certified EIFS inspector to determine condition.

DOORS AND WINDOWS

These can waste an enormous amount of energy. Maintain the caulking around the frames on the exterior. Check for drafts in the winter and improve the worst offenders first. Windows that have leaky storm windows will usually have a lot of sweating. Likewise, well-sealed storms that sweat indicate a leaky window. It is the tighter unit that will sweat (unless the home has excess humidity to begin with).

Wood that exhibits blistering or peeling paint should be examined for possible moisture sources: roof leaks, bad gutters, interior moisture from baths or laundry or from a poorly vented crawl space. Some paint problems have no logical explanation, but many are a symptom of an underlying problem. A freshly painted house may mask these symptoms, but after you have lived in the home for a year or two, look for localized paint blistering (peeling). It may be a clue.

New glazing will last longer if the raw wood is treated with boiled linseed oil prior to glazing. It prevents the wood from drawing the moisture out of the new glazing.

CAULKING

Many different types of caulk are available on the market today. Check with a paint or hardware store for the kind of application you need.

Garage Remarks

OVERHEAD DOOR OPENERS

We recommend that a separate electrical outlet be provided. Openers that do not have a safety reverse are considered a safety hazard. Small children and pets are especially vulnerable. We recommend the operating switches be set high enough so children cannot reach them. If an electric sensor is present, it should be tested occasionally to ensure it is working.

GARAGE SILL PLATES

Should be elevated or treated lumber should be used. If this is not the case, try to direct water away to prevent rotting.

BU	ID	N	Tr'	D	C
Dι	JN	ΙT	L.	N	7

Any appliance such as a water heater, f	furnace, etc. should have the flam	ne a minimum of 18" abov	ve the floor. Any open flame	e less than
18" from the floor is a potential safety	hazard. The appliance should also	o be protected from vehic	ele damage.	

Interior Remarks

PLASTER ON WOOD LATH

Plaster on wood lath is an old technique and is no longer in general use. Wood lath shrinks with time and the nails rust and loosen. As a result, the plaster may become fragile and caution is needed in working with this type of plastering system. Sagging ceilings are best repaired by laminating drywall over the existing plaster and screwing it to the ceiling joists.

PLASTER ON GYPSUM LATH (ROCK LATH)

Plaster on gypsum lath will sometimes show the seams of the 16" wide gypsum lath, but this does not indicate a structural fault. The scalloping appearance can be leveled with drywall joint compound and fiberglass mesh joint tape or drywall can be laminated over the existing plaster on the ceiling.

WOOD FLOORING

Always attempt to clean wood floors first before making the decision to refinish the floor. Wax removers and other mild stripping agents plus a good waxing and buffing will usually produce satisfactory results. Mild bleaching agents help remove deep stains. Sanding removes some of the wood in the floor and can usually be done safely only once or twice in the life of the floor.

NAIL POPS

Drywall nail pops are due to normal expansion and contraction of the wood members to which the drywall is nailed and are usually of no structural significance.

CARPETING

Where carpeting has been installed, the materials and condition of the floor underneath cannot be determined.

APPLIANCES

(If report indicated appliances were operated, the following applies) dishwashers are tested to see if the motor operates and water sprays properly. Stoves are tested to see that burners are working and oven and broiler get hot. Timer and controls are not tested. Refrigerators are not tested. Most new dishwashers have the drain line looped automatically and may not be visible on the day of inspection. It is essential for the dishwasher drain line to have an anti-siphon break to prevent backflow. A drain line loop or Dishwasher air gap should be installed if found to be missing. No representation is made to continued life expectancy of any appliance.

ASBESTOS AND OTHER HAZARDS

Asbestos fibers in some form are present in many homes, but are often not visible and cannot be identified without testing.

If there is reason to suspect that asbestos may be present and if it is of particular concern, a sample of the material in question may be removed and analyzed in a laboratory. However, detecting or inspecting for the presence or absence of asbestos is not a part of our inspection.

Also excluded from this inspection and report are the possible presence of, or danger from, radon gas, lead-based paint, urea formaldehyde, toxic or flammable chemicals and all other similar or potentially harmful substances and environmental hazards.

WINDOWS

A representative number of windows are inspected.

DOOR STOPS

All swinging doors should be checked for door stops. Broken or missing door stops can result in door knobs breaking through drywall or plaster.

CLOSET GUIDES

Sliding closet doors should be checked to see that closet guides are in place. Missing or broken closet guides can cause scratches and damage to doors.

COLD AIR RETURNS

Bedrooms that do not have cold air returns in them should have a 3/4" gap under the doors to allow cold air to be drawn into the hall return.

Interior Remarks

AN INSPECTION VERSUS A WARRANTY

A home inspection is just what the name indicates, an inspection of a home...usually a home that is being purchased. The purpose of the inspection is to determine the condition of the various systems and structures of the home. While an inspection performed by a competent inspection company will determine the condition of the major components of the home, no inspection will pick up every minute latent defect. The inspectors ability to find all defects is limited by access to various parts of the property, lack of information about the property and many other factors. A good inspector will do his or her level best to determine the condition of the home and to report it accurately. The report that is issued is an opinion as to the condition of the home. This opinion is arrived at by the best technical methods available to the home inspection industry. It is still only an opinion.

A warranty is a policy sold to the buyer that warrants that specific items in the home are in sound condition and will remain in sound condition for a specified period of time. Typically, the warranty company never inspects the home. The warranty company uses actuarial tables to determine the expected life of the warranted items and charges the customer a fee for the warranty that will hopefully cover any projected loss and make a profit for the warranty seller. It is essentially an insurance policy.

The service that we have provided you is an inspection. We make no warranty of this property. If you desire warranty coverage, please see your real estate agent for details about any warranty plan to which their firm may have access.

WINDOW FRAMES AND SILLS

Window frames and sills are often found to have surface deterioration due to condensation that has run off the window and damaged the varnish. Usually this can be repaired with a solvent style refinisher and fine steel wool. This is sometimes a sign of excess humidity in the house. See comments regarding caulking doors and windows, page 8.

FIREPLACES

It is important that a fireplace be cleaned on a routine basis to prevent the buildup of creosote in the flue, which can cause a chimney fire. Masonry fireplace chimneys are normally required to have a terra cotta flue liner or 8 inches of masonry surrounding each flue in order to be considered safe and to conform with most building codes. During visual inspections, it is not uncommon to be unable to detect the absence of a flue liner either because of stoppage at the firebox, a defective damper or lack of access from the roof.

WOODBURNERS

Once installed, it can be difficult to determine proper clearances for woodburning stoves. Manufacturer specifications, which are not usually available to the inspector, determine the proper installation. We recommend you ask the owner for paperwork, verifying that it was installed by a professional contractor.

VENTILATION

Ventilation is recommended at the rate of one square foot of vent area to 300 square feet of attic floor space, this being divided between soffit and rooftop. Power vents should ideally have both a humidistat and a thermostat, since ventilation is needed to remove winter moisture as well as summer heat. Evidence of condensation such as blackened roof sheathing, frost on nail heads, etc. is an indication that ventilation may have been or is blocked or inadequate.

INSULATION

The recommended insulation in the attic area is R-38, approximately 12". If insulation is added, it is important that the ventilation is proper.

SMOKE DETECTORS

Smoke detectors should be tested monthly. At least one detector should be on each level. CO detectors are not required by most states, but for safety reasons, are highly recommended.

VAPOR BARRIERS

The vapor barrier should be on the warm side of the surface. Most older homes were built without vapor barriers. If the vapor barrier is towards the cold side of the surface, it should be sliced or removed. Most vapor barriers in the attic are covered by insulation and therefore, not visible.

Interior Remarks

SAFETY GLAZING

Safety glazing requirements vary depending on the age of the home. Every attempt is made to identify areas where the lack of safety glazing presents an immediate safety hazard, such as a shower door. In some older homes it is difficult to determine if safety glazing is present, since the glass is not marked. Therefore, no representation is made that safety glazing exists in all appropriate areas.

INSULATED GLASS

Broken seal in thermopane/insulated windows are not always visible nor detectible due to humidity and temperature changes during the
day. Other factors such as window covering, dirty windows, and lack of accessibility, personal property placed in front of the windows al
affect the view of the windows at the time of the inspection.

Bathroom(s) Remarks

STALL SHOWER

The metal shower pan in a stall shower has a potential or probable life of 10-20 years depending on quality of the pan installed. Although a visible inspection is made to determine whether a shower pan is currently leaking, it cannot be stated with certainty that no defect is present or that one may not soon develop. Shower pan leaks often do not show except when the shower is in actual use.

CERAMIC TILE

Bathroom tile installed in a mortar bed is excellent. It is still necessary to keep the joint between the tile and the tub/shower caulked or sealed to prevent water spillage from leaking through and damaging the ceilings below.

Ceramic tile is often installed in mastic. It is important to keep the tile caulked or water will seep behind the tile and cause deterioration in the wallboard. Special attention should be paid to the area around faucets and other tile penetrations.

EXHAUST FANS

Bathrooms with a shower should have exhaust fans when possible. This helps to remove excess moisture from the room, preventing damage to the ceiling and walls and wood finishes. The exhaust fan should not be vented into the attic. The proper way to vent the fan(s) is to the outside. Running the vent pipe horizontally and venting into a gable end or soffit is preferred. Running the vent pipe vertically through the roof may cause condensation to run down the vent pipe, rusting the fan and damaging the wallboard. Insulating the vent pipe in the attic will help to reduce this problem.

SLOW DRAINS

Slow drains on sinks, tubs, and showers are usually due to build up of hair and soap scum. Most sink popups can be easily removed for cleaning. Some tubs have a spring attached to the closing lever that acts as a catch for hair. It may require removing a couple of screws to disassemble. If you cannot mechanically remove the obstruction, be kind to your pipes. Don't use a caustic cleaner. There are several bacteria drain cleaners available. They are available at hardware stores in areas where septic tanks are used. These drain cleaners take a little longer to work, but are safe for you and your pipes.

SAFETY HAZARDS

Typical safety hazards found in bathrooms are open grounds or reverse polarity by water. Replacing these outlets with G.F.C.I.'s are recommended.

WHIRLPOOL TUBS

This relates to interior tubs hooked up to interior plumbing. Where possible, the motor will be operated to see that the jets are working. Hot tubs and spas are not inspected.

Basement Remarks

BASEMENT/CRAWLSPACE

Any basement/crawlspace that has cracks or leaks is technically considered to have failed. Most block basements/crawlspace have step cracks in various areas. If little or no movement has occurred and the step cracks are uniform, this is considered acceptable. Horizontal cracks in the third or fourth block down indicate the block has moved due to outside pressure. They can be attributed to many factors such as improper grading, improperly functioning gutter and downspout system, etc. Normally if little or no movement has taken place and proper grading and downspouts exist, this is considered acceptable. If the wall containing the stress crack(s) has moved considerably, this will require some method of reinforcement. Basements/crawlspace that have been freshly painted or tuckpointed should be monitored for movement. This will be indicated by cracks reopening. If cracks reappear, reinforcement may be necessary. Reinforcing a basement/crawlspace wall can become expensive.

FOUNDATION (COVERED WALLS)

Although an effort has been made to note any major inflections or weaknesses, it is difficult at best to detect these areas when walls are finished off, or basement/crawlspace storage makes areas inaccessible. No representation is made as to the condition of these walls.

INSULATED CONCRETE FORMS (ICF'S)

Formwork for concrete that stays in place as permanent building insulation for energy-efficient, cast-in-place, reinforced concrete walls, floors and roofs.

MONITOR

Indicates that the walls have stress cracks, but little movement has occurred. In our opinion, the cracks should be filled with mortar and the walls monitored for further movement and cracking. If additional movement or cracking occurs, reinforcement may be necessary.

HAVE EVALUATED

We recommend that the walls be re-evaluated by a structural engineer or basement/crawlspace repair company and estimates be obtained if work is required.

VAPOR BARRIER

Floors that are dirt or gravel should be covered with a vapor barrier.

MOISTURE PRESENT

Basement/crawlspace dampness is frequently noted in houses and in most cases the stains, moisture or efflorescence present is a symptom denoting that a problem exists outside the home. Usual causes are improper downspout extensions or leaking gutters and/or low or improper grade (including concrete surfaces) at the perimeter of the house. A proper slope away from the house is one inch per foot for four to six feet. Expensive solutions to basement/crawlspace dampness are frequently offered. It is possible to spend thousands of dollars on solutions such as pumping out water that has already entered or pumping of chemical preparations into the ground around the house, when all that may be necessary are a few common sense solutions at the exterior perimeter. However, this is not intended to be an exhaustive list of causes and solutions to the presence of moisture. No presentation is made to future moisture that may appear.

PALMER VALVE

Many older homes have a valve in the floor drain. This drain needs to remain operational.

DRAIN TILE

We offer no opinion about the existence or condition of the drain tile, as it cannot be visibly inspected.

BASEMENT ELECTRICAL OUTLETS

We recommend that you have an outlet within 6' of each appliance. The appliance you plan to install may be different than what exists, therefore the inspection includes testing a representative number of receptacles that exist. It is also recommended to have ground fault circuit interrupts for any outlet in the unfinished part of the basement and crawl spaces.

Plumbing Remarks

WELLS

Examination of wells is not included in this visual inspection. It is recommended that you have well water checked for purity by the local health authorities and, if possible, a check on the flow of the well in periods of drought. A well pit should have a locked cover on it to prevent anyone from falling into the pit.

SEPTIC SYSTEMS

The check of septic systems is not included in our visual inspection. You should have the local health authorities or other qualified experts check the condition of the septic system. In order for the septic system to be checked, the house must have been occupied within the last 30 days.

WATER PIPES

Galvanized water pipes rust from the inside out and may have to be replaced within 20 to 30 years. This is usually done in two stages: horizontal piping in the basement first, and vertical pipes throughout the house later as needed. Copper pipes usually have more life expectancy and may last as long as 60 years before needing to be replaced.

HOSE BIBS

During the winter months it is necessary to make sure the outside faucets are winterized. This can be done by means of a valve located in the basement. Leave the outside faucets open to allow any water standing in the pipes to drain, preventing them from freezing. Hose bibs cannot be tested when winterized.

WATER HEATER

The life expectancy of a water heater is 5-10 years. Water heaters generally need not be replaced unless they leak. It is a good maintenance practice to drain 5-10 gallons from the heater several times a year. Missing relief valves or improper extension present a safety hazard.

WATER SOFTENERS

During a visual inspection it is not possible to determine if water is being properly softened.

PLUMBING

The temperature/pressure valve should be tested several times a year by lifting the valves handle. Caution: very hot water will be discharged. If no water comes out, the valve is defective and must be replaced.

SHUT-OFF VALVES

Most shut-off valves have not been operated for long periods of time. We recommend operating each shut-off valve to: toilet bowl, water heater, under sinks, main shut-off, hose faucets, and all others. We recommend you have a plumber do this, as some of the valves may need to be repacked or replaced. Once the valves are in proper operating order, we recommend opening and closing these valves several times a year.

POLYBUTYLENE PIPING

This type of piping has a history of problems and should be examined by a licensed plumber and repaired or replaced as necessary.

MECHANICAL DEVICES MAY OPERATE AT ONE MOMENT AND LATER MALFUNCTION; THEREFORE, LIABILITY IS SPECIFICALLY LIMITED TO THOSE SITUATIONS WHERE IT CAN BE CONCLUSIVELY SHOWN THAT THE MECHANICAL DEVICE INSPECTED WAS INOPERABLE OR IN THE IMMEDIATE NEED OF REPAIR OR NOT PERFORMING THE FUNCTION FOR WHICH IS IT WAS INTENDED AT THE TIME OF INSPECTION.

CSST

Corrugated Stainless Steel Tubing is an alternative to traditional black iron gas piping. It is a continuous, flexible, stainless steel pipe with an exterior PVC covering.

Heating System Remarks

Heating and air conditioning units have limited lives.

Normal lives are:

GAS-FIRED HOT AIR	15-25 years
OII-FIRED HOT AIR	20-30 years
CAST IRON BOILER	30-50 years
STEEL BOILER	30-40 years
COPPER BOILER	10-20 years
CIRCULATING PUMP (Hot water)	10-15 years
AIR CONDITIONING COMPRESSOR	8-12 years
HEAT PUMP	8-12 years

Gas-fired hot air units that are close to or beyond their normal lives have the potential of becoming a source of carbon monoxide in the home. You may want to have such a unit checked every year or so to assure yourself that it is still intact. Of course a unit of such an age is a good candidate for replacement with one of the new, high efficiency furnaces. The fuel savings alone can be very attractive.

Boilers and their systems may require annual attention. If you are not familiar with your system, have a heating contractor come out in the fall to show you how to do the necessary thing Caution: do not add water to a hot boiler!

Forced air systems should have filters changed every 30 to 60 days of the heating and cooling season. This is especially true if you have central air conditioning. A dirty air system can lead to premature failure of your compressor - a \$1,500 machine.

Oil-fired furnaces and boilers should be serviced by a professional each year. Most experts agree you will pay for the service cost in fuel saved by having a properly tuned burner.

Read the instructions for maintaining the humidifier on your furnace. A malfunctioning humidifier can rust out a furnace rather quickly. It is recommended that the humidifier be serviced at the same time as the furnace, and be cleaned regularly. During a visual inspection it is not possible to determine if the humidifier is working.

Have HVAC technician examine - A condition was found that suggests a heating contractor should do a further analysis. We suggest doing this before closing.

Heat exchangers cannot be examined nor their condition determined without being disassembled. Since this is not possible during a visual, non-technically exhaustive inspection, you may want to obtain a service contract on the unit or contact a furnace technician regarding a more thorough examination.

Testing pilot safety switch requires blowing out the pilot light. Checking safety limit controls requires disconnecting blower motor or using other means beyond the scope of this inspection. If the furnace has not been serviced in last 12 months you may want to have a furnace technician examine.

CO Test - This is not part of a non-technical inspection. If a test was performed, the type of tester is indicated on page 27.

Combustible Gas Detector - If a gas detector was used during the inspection of the furnace and evidence of possible combustible gases was noted, we caution you that our test instrument is sensitive to many gases and not a foolproof test. None-the-less, this presents the possibility that a hazard exists and could indicate that the heat exchanger is, or will soon be, defective.

Preventive Maintenance Tips

I. Foundation and Masonry:

Basements, Exterior Walls: To prevent see page and condensation problems.

- a. Check basement for dampness and leakage after wet weather
- b. Check chimneys, deteriorated chimney caps, loose, and missing mortar.
- c. Maintain grading sloped away from foundation walls.

II. Roofs, Gutters, and Eavestrough:

To prevent roof leaks, condensation, see page and decay problems.

- a. Check for damaged, loose, or missing shingles, blisters.
- b. Clean gutters, leaders, strainers, window wells, drains. Be sure downspouts direct water away from foundation.
- c. Cut back tree limbs.
- d. Check flashings around roof stacks, vents, skylights, chimneys as source of leakage.
- e. Check vents, louvers and chimneys for birds nests, squirrels, insects.
- f. Check fascias and soffits for paint flaking leakage and decay.

III. Exterior Walls:

To prevent paint failure, decay, and moisture penetration problems.

- a. Check painted surface for paint flaking or paint failure. Check back shrubs.
- b. Check exterior masonry walls for cracks, looseness, missing or broken mortar.

IV. Doors and Windows:

To prevent air and weather penetration problems.

- a. Check caulking for decay around doors, windows, corner boards, joints.
- b. Recaulk and weatherstip as needed. Check glazing putty around windows.

V. Electrical:

For safe electrical performance, mark and label each circuit.

- a. Trip circuit breakers every six months and ground fault circuit interrupters (G.F.C.I.) monthly.
- b. Check condition of lamp cords, extension cords and plugs. Replace at first sign of wear and damage.
- c. Check exposed wiring and cable for wear or damage.
- d. If you experience slight tingling shock from handling or touching any appliance, disconnect the appliance and have it repaired. If lights flicker or dim, or if appliances go on and off unnecessarily, call a licensed electrician.

VI. Plumbing:

For preventive maintenance.

- a. Drain exterior water lines, hose bibbs, sprinklers, pool equipment in the fall.
- b. Draw off sediment in water heaters monthly or per manufacturer's instructions.
- c. Have septic tank cleaned every 2 years.

VII. Heating and Cooling:

For comfort, efficiency, energy conservation and safety.

- a. Change or clean furnace filters, air condition filters, electronic filters as needed.
- b. Clean and service humidifier. Check periodically and annually.
- c. Have oil burning equipment serviced annually.

VIII. Interior

General house maintenance.

- a. Check bathroom tile joins, tub grouting and caulking. Be sure all tile joints in bathrooms are kept well sealed with tile grout to prevent damage to walls, floors, and ceilings below.
- b. Close crawl vents in winter and open in summer
- c. Check underside of roof for water stains, leaks, dampness & condensation, particularly in attics and around chimneys.

IX. Know the location of:

- -Main water shutoff valve.
- -Main emergency shutoff switch for the heating system.
- -Main electrical disconnect or breaker.